GAUSS

ELÉTRICA INJEÇÃO IGNIÇÃO ARREFECIMENTO

MEDIDOR DE FLUXO DE AR

GH5003



SUBSTITUI:
Bosch: 0 280 218 019
APLICAÇÃO:
ALFA: 145(930) 1.6 i.e.16V T.S.Hatchback 12.96-01.01 88 120 1598,145(930) 1.6 i.e.16V Hatchback 03.98-01.01 106 144 1598;
FIAT: Brava(182) 1.9 JTD 105 Hatchback 12.98-10.01 77 105 1910

GH5013



SUBSTITUI:
Bosch: 0 280 218 013; **VW:** 06B 133 471
APLICAÇÃO:
AUDI: A4 1.8 94-01 92 125 1781, A6 /Avant 1.8 99-01 92 125 1781;
VW: Passat /Variant 1.8 96-03 92 125 1781.

GH5014



SUBSTITUI:
Bosch: 0 280 218 060; **VW:** 06A 906 461G
APLICAÇÃO:
AUDI: A3 1.8 98-03 92 125 1781, Audi Q7 4.2 FSI 06.08;
SEAT: Cordoba 2.0, Saloon 09.02 85 115 1984;
VW: Bora 2.0 10.98 85 115 1984, Golf IV 1.6 03-78 107 1595, Golf IV 2.0 01.07 85 115 1984, New Beetle 2.0 00-05 85 115 1984, New Beetle 1.8 T 04.05 150, Phaeton 4.2 V8 03-246 335 4172, Touareg 4.2 V8 02.06 228 310 4172.

GH5015



SUBSTITUI:
Bosch: 0 280 218 063, 280218064; **VW:** 06A 906 461L
APLICAÇÃO:
AUDI: A4 1.8 T Saloon/ Quat 00-04 110 150 1781, A3 1.8 T 150CV 12.96 110 150 1781, A3 1.8T 180CV 00-03 180, A6 1.8 T 00-06 110 150 1781, TT 1.8 T 180CV 00-06 132 180 1781, TT 1.8 T 150 CV 01.06 150;
VW: Bora 1.8T 150CV 00-05, 180CV 02-03, Golf IV 1.8 T 150CV 00-03, 180CV 02-07, New Beetle 1.8 T 150CV 00-04, 180CV 01-05, Passat /Variant 1.8 T 00-05, Polo 1.8 GTI 05-, Jetta IV 1.8T 03.04 180CV;
SEAT: Ibiza IV 1.8 T 03>.

GH5024



SUBSTITUI:
Bosch: 0 280 218 002, 0 986 280 205, 0 280 218 003; **VW:** 06A 906 461 A
APLICAÇÃO:
AUDI: A3 1.8 96-06 125 CV, A4 1.8T 99-00 112 CV;
SEAT: Toledo II 1.8 20 V 04.99 125 CV;
VW: Bora 2.0 98-05 115 CV, Bora 1.8 98-00 125CV, Golf IV 1.8 97-00 125 CV, Golf IV 2.0 98-05 115 CV, New Beetle 1.8 T 98-01 150 CV, **New** Beetle 2.0 98-05 115 CV

GH5027



SUBSTITUI:
Bosch: 0 280 217 117; **VW:** 037 906 461 C; **Ford:** 98; **VW** 12B529 BA
APLICAÇÃO:
AUDI: A3 1.8 T 99-06 110 150 1781, A4 / Avant 1.8 T 97-01 132 180 1781, A6 / Avant 1.8 T 150CV 97-99, 180 CV 97-00;
VW: Bora 1.8 T 00-05 110 150 1781, Golf IV Gti 1.8 T 99-02 110 150 1781, Passat/ Variant 1.8 T 99-00 110 150 1781.

GH5031



SUBSTITUI:
Siemens: 5WK9623; **Hella:** 8ET 009 142-141; **Citroën:** 1920.8Q; **Fiat:** 9628336380; **Peugeot:** 1920.8Q

APLICAÇÃO:
CITROËN: Jumper Box 2.0 HDI 02, Jumper Box 2.2 HDI 02, Jumper Bus 2.0 HDI 02, Jumper Bus 2.2 HDI 02, Jumper Flabted/Chassis 2.0 HDI 02, Jumper Flabted/Chassis 2.2 HDI 02;
FIAT: Ducato Box 2.0 JTD 01- 02, Ducato Box 2.0 JTD 02, Ducato Bus 2.0 JTD 01- 02, Ducato Bus 2.0 JTD 02, Ducato Flatbed/Chassis 2.0 JTD 02;
PEUGEOT: Boxer Box 2.0 HDI 02, Boxer Box 2.2 HDI 02, Boxer Bus 2.0 HDI 02, Boxer Bus 2.2 HDI 02, Boxer Flatbed /Chassis 2.0 HDI 02, Boxer Flatbed /Chassis 2.2 HDI 02.

GH5032



SUBSTITUI:
Bosch: 0 280 218 108; **Volvo:** 8670112, 8670263

APLICAÇÃO:
VOLVO: C70 2.0 T, 2.3 T, 2.5T 98-02 166 226 1984, Volvo S60 2.4 T 00-03 147 200 2435, Volvo S70 2.0, 2.3T, 2.4T 97-00 120 163 1984, Volvo S80 2.0, 2.0T, 2.4T, 2.9 98-06 120 163 1984, Volvo V70 I 2.0, 2.0T, 2.3, 2.4T, 2.5, 2.5T 97-00 120 163 1984, Volvo XC70 Cross Coutry 2.4 T XC AWD 00-02 147 200 2435

GH5033

SUBSTITUI:
Siemens: 5WK9621; **Fiat:** 9629471080; **Citroën/ Peugeot:** 1920.7S

APLICAÇÃO:
CHEVROLET: Tracker 2.0 Diesel 2001>2004;
CITROËN: Berlingo 1.8 1998>2002, Xantia 2.0 1994>2001;
PEUGEOT: 306 2.0 1992>2001, 307 1.6 2002>2012, 406 2.0 1997>2003, 806 2.0 1995>2000;
SUZUKI: Vitara 2.0 Diesel com motor peugeot 1998>2003

GH5041



SUBSTITUI:
Bosch: 0 280 218 032, 0 280 218 033; **VW:** 06A 906 461 D

APLICAÇÃO:
AUDI: A3 1.8 T 150CV 99-03, 180CV 00-06, A4 1.8 T 150CV 08-00, A6 / Avant 1.8 T 150CV 98-01 , TT 1.8 T 180CV 98-01;
SEAT: Cordoba 1.8 T 20V Cupra 99-02 , Ibiza III 1.8 T 20V Cupra 99-02;
VW: Golf IV 1.8 T 150CV 99-00, Passat / Variant 1.8 T 150CV 99-00.

GH5047



SUBSTITUI:
Kia: 0K08013210

APLICAÇÃO:
KIA: Sportage 2000 cc MOT.2.0 i.e 03.99 2000

GH5052



SUBSTITUI:
Bosch: 0 280 217 111; **Fiat:** 60810813; **Alfa Romeo:** 46407008

APLICAÇÃO:
ALFA ROMEO: 145(930) 1.6, 1.7i 16V T.S. Hatchback 10.94-12.96 88 120 1598, 145(930) 1.8, 2.0 16V Hatchback 03.98-01.01 106 1441747, 145(930) 2.0 16V T.S. Hatchback 10.95-01.01 110 150 1970, 146(930) 1.6, 1.7, 1.8, 2.0 16V T.S. Hatchback 11.96-01.01 88 120 1598, 155(167) 1.6, 1.7, 2.0 16V T.S. Saloon 05.96-01.98 88 120 1598, 156(932) 1.6 16V T.Spark(932A4) Saloon 09.97 88 120 1598, Spider(916S_) 2.0 T.Spark 16V(916S2C00) 06.95 110 150 1970;
FIAT: Brava (182) 2.0 HGT 20V (182.AD) Hatchback 10.95-07.98 108 147 1998, Coupe (FA/175) 2.0 20V 96-98 108 147 1998, Marea / Weekend 2.0 20V 98-00 108 147 1998, Coupe 2.0 20V 96-98

GH5061



SUBSTITUI:
VW: 06A906461B; **Hella:** 8ET 009 142-261
APLICAÇÃO:
AUDI: A3 1.6 96- 74 101 1595, AUDI A4 / Avant 1.6 95-00 74 100 1595;
SEAT: Cordoba 1.6 99-02 74 101 1595, Ibiza III 1.6 99-02 74 101 1595;
VW: Golf IV 1.6 Hatchback 97-00 74 100 1595, Passat/Variant 2.0 00- 85 115 1984, Polo Classic 1.6 95-01 74 100 1595, Transporter IV Box 2.5 96- 85 115 2461

GH5063



SUBSTITUI:
Bosch: 0 281 217 112, 0 280 217 013; **VW:** 058 133 471 A
APLICAÇÃO:
AUDI: A3 1.8 T 96-03 110 150 1781, A4 / Avant 1.8 T 94-98 110 150 1781, A6 1.8 T 97-99 110 150 1781;
VW: Passat / Variant 1.8T 96-00 110 150

GH5078



SUBSTITUI:
Bosch: 0 281 002 531; **VW:** 038 906 461B
APLICAÇÃO:
WV: Golf IV 2.0 99-02, Bora 1.8 98-00, New Beetle 1.8T 98-01;
AUDI: A3 1.8 99-06.

GH5080 // NOVIDADE //

SUBSTITUI:
Bosch: 0 281 002 184; **Citroën:** 1192 W5; **Fiat:** 13243690, 13244369080, 717359980; **Iveco:** 5045051082; **Opel:** 90 528 435, 91 93 533; **Peugeot:** 1192 W5
APLICAÇÃO:
CITROËN: Jumper 2.8 HDI 2005>2009;
PEUGEOT: Boxer 2.8 HDI 2005>2009;
FIAT: Ducato 2.8 JTD 2002>2006

GH5091



SUBSTITUI:
Ford: 1 030 844, 96 FP12B579 AB; **Pieburg:** 7.22184.04.0
APLICAÇÃO:
FORD: Fiesta IV 1.4 I 16V 04.92-01.02 66 90 1388, Fiesta 1.4 16V 11.01 59 80 1388, Ka 1.3 09.96, 08.02 44 60 1299.

GH5093



SUBSTITUI:
Hella: 8ET 009 142-171; **Ford:** 93BB12B579BA, 6 848 047
APLICAÇÃO:
FORD: Escort 1.8 16V, Mondeo 1.8 16V 94-96.

GH5125

SUBSTITUI:
Bosch: 0 280 217 002;
Volvo: 1356220
APLICAÇÃO:
VOLVO: 850 2.5 GLT 1991>1996 (gasolina)

GH5209 // NOVIDADE //

SUBSTITUI:
Bosch: 0 280 218 2019;
GM: 13 241 771
APLICAÇÃO:
GM: Agile 2009>2014, Montana G2 1.4/1.8 2011>2016

GH5682

SUBSTITUI:
Bosch: 0 280 218 254; **Chevrolet:** 13301682
APLICAÇÃO:
CHEVROLET: Cruze 1.8 16V 2012>, Onix 1.0/1.4 16V 2012>, Sonic 1.6 2013>, Spin 1.8 2013>

GH5980

SUBSTITUI:
Denso: 197400-5220;
Honda: 37980-RLF-003, 37980-R11-A01, 37980-R11-WZZ, 37980-R40-AA0, 37980-R40-A01
APLICAÇÃO:
HONDA: Civic Touring CVT 1.5 Turbo 2017>